

Big Valley Sanitation

5551 Eastside Rd, Redding CA 96001 • 530-243-0657

SEPTIC INSPECTION CERTIFICATE

Date: 7/11/18

The septic system was pumped and inspected for Majka Real Estate
(Customer Name)

on the above date at 7693 Linda Rd, Shingletown CA
(Address, City, State)

The following items were inspected and noted:

Make of Tank: Concrete Plastic Metal Other _____

Chambers: Single Dual Lids: 2 concrete

Tank capacity (gallons): 1100 Depth of tank: 8"

Tank dimensions: _____

Distance from house: vacant lot

Leach field location: south west of tank

Inflow tee properly installed: Yes No

Outflow tee properly installed: Yes No

Inlet clear and appears to be functioning properly: Yes No

Outlet clear and appears to be functioning properly: Yes No

Tank inspected for cracks and leakage: Yes No

Leach field seems to be working properly: Yes No

Notes: Tank in good condition and appears to be functioning properly.

The septic system has passed inspection: Yes No

Technician's Signature: Sean Winchell